

MONUMENT RECORD
State of Indiana - County of Monroe

Section: 31 SW

Township: 7N

Range: 2 E

Corner ID: TwpCor IV

Monument Description & Remarks: 5/8" rebar in knee deep cold water.

References On File: Kenneth Anderson survey in Recorder's book 3 page 286.


Field Book: 2000-02

Page No.: 28

USGS Quad: Norman

3	1


Tie Sheet Drawing
(Not to Scale)



A-5/8" rebar with aluminum cap in knee deep cold water
B-N 77 ° W 13.76' to MAG nail in 8" sugar maple. Survey Marker 5' A.G.
C-S 25 ° E 46.28' to MAG nail in 15" sycamore
D-S 87 ° E 65.98' to 2 1/2 aluminum cap "WITNESS"

I, Kevin P. Enright, Monroe County Surveyor, hereby certify that this document was prepared under my direction in accordance with the provisions of Section 36-2-12-11 of the Indiana Code; and the above data is given under my hand this 3rd day of October, 2000.

Kevin P. Enright



Certified and sealed by the Monroe County Surveyor Review Board


Date: December 14, 2000

November 28, 2000

T. 6 & 7 N R. 1 & 2 E 2nd Mer. N.F. Hoosier County Monroe/Lawrence State Indiana
Township Corner common to sections 1 6 31 and 36

EXISTING SURVEYS

Original Government Survey		Original Evidence Found	
Year surveyed <u>1811</u>	<u>Alexander Holmes</u>	Year of search <u>1986</u>	By <u>V.H.M., R.A.G. & R.C.E.</u>
Original monument <u>Wood Post</u> <small>(wood post, stone, pile of stones, pipe, etc.)</small>		Monument found <u>None</u>	
Bearing Trees		Original Bearing Trees Found	
Species <u>Sugar</u>	<u>Hickory</u>	Species <u>None</u>	
Diameter <u>16"</u>	<u>14"</u>	Diameter	
Bearing <u>S 32 E</u>	<u>N 14 E</u>	Bearing	
Distance <u>11 Lks.</u>	<u>28 Lks.</u>	Distance	
Subsequent Corner Restoration		Evidence of Subsequent Corner Restoration Found	
Year surveyed <u>1859</u>	By <u>James W. Spencer</u>	Year of search <u>1986</u>	By <u>V.H.M., R.A.G. & R.C.E.</u>
Where filed or recorded <u>Monroe Co. Survey Book, Pg. 10</u>		Monument found <u>None</u>	
Monument <u>Does not say what monument, if any, was set</u>			
Bearing Trees, Reference Objects			
Species <u>Sycamore</u>	<u>W. Oak</u>		
Diameter <u>10"</u>	<u>12"</u>		
Bearing <u>N 5 W</u>	<u>N 77 E</u>		
Distance <u>110 1/2 Lks.</u>	<u>197 Lks.</u>		



Sketch

O Corner ☒ F.S. Land

Relation of Evidence to Record Features Along Section Lines

Section line to sections	Object	Record distance	Measured distance
<u>31 & 6</u>	<u>Creek 50 Lks SW</u>	<u>1.50 chs</u>	
<u>1 & 6</u>	<u>Creek 50 Lks SW</u>	<u>.50 chs</u>	

Other Evidence

Describe evidence of use and occupation such as roads, fences, clearings, timber cutting lines, plantations, etc. Cite source of testimony if any. Corner is situated near the northerly bank of Hunter Creek. This area is cultivated very near the creek bank, which is sloughing off in this vicinity. If any corner monument was in this vicinity, it is lost or destroyed.

At time of search:

1. Did you have the record description?
Yes X No ---

2. How was search area located?

Pacing, chaining, photos, maps, etc. chaining3. Man hours spent in search 2 1/24. Do you think additional search might recover evidence? Yes --- No X5. Signature Vict H McCarly

Perpetuation Record

Monument and accessories established. Include brief description of area. Set 30" x 1/2" rebar with 1 1/2" aluminum cap stamped to identify corner.

Unmarked Accessories Established:

Witness

Sycamore	Blue Beech	Sycamore	Cherry	Monument
<u>11"</u>	<u>8"</u>	<u>14"</u>	<u>12"</u>	
<u>East</u>	<u>S 67 E</u>	<u>S 29 E</u>	<u>S 40 W</u>	<u>S 89° 47' 54" E</u>
<u>47.7'</u>	<u>38.8'</u>	<u>46.2'</u>	<u>73.4'</u>	<u>66.0'</u>

Certified corner restoration certificate prepared: Yes --- No ---Filed in county records at --- Date --- County Document No. ---Identified on aerial photo No. --- Which is filed at ---